

$S_p = 6,5 \text{ mA/V}$
 $R_i = 200 \text{ k}$
 $P_a = \text{max} = 3 \text{ W}$

$S_T = 8 \text{ mA/V}$
 $R_i = 5 \text{ k}$
 $\mu = 40$
 $P_a = \text{max} = 2,5 \text{ W}$

