



$S_F = 9 \text{ mA/V}$
 $R_i = 230 \text{ k}$
 $\mu_{g2g1} = 46$
 $P_a = 2,5 \text{ W}$



$S_L = 20 \text{ mA/V}$
 $R_i = 50 \text{ k}$
 $\mu_{g2g1} = 38$
 $P_a = 5 \text{ W}$